

Menu


HISTORY FILE MAP for year 2005

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



090.01:45 – 01:47 2m RT 1024bps data lost due to 2way to 1way transition at DSS24 followed by
01:55 – 02:04 9m data loss due to 1way to 2way transition due to transmitter trip off following
an open interlock/waveguide arc critical alarm. DR G105502 refers.